


Peta Kontur



Grafik Eb/No Vs BER

MINI-LINK Service Manager - [Control Operator]

Setup Log View Misc Window Help

961a: MLE_1+0 Major

ALARMS

Alarm
B-Alarm

Control and Status

Power	Off	Tx	Rx +22.0dBm
Loop	Off		
Test Port	Off		
Transmitter	On	Rx	Rx -37.5dBm

914a: MLE_1+0 Minor

ALARMS

Alarm
B-Alarm

Control and Status

Power	Off	Tx	Rx +22.0dBm
Loop	Off		
Test Port	Off		
Transmitter	On	Rx	Rx -39.7dBm

Scan


Scanning is in progress .

Press (Ctrl+B) to break.

Break

2006 Nov 20 13:40:39 370a Alarm Notification

2006 Nov 20 13:41:07



MINI-LINK Service Manager - [Control Operator]

Setup Log View Misc Window Help

966: MLE_1+1 Major

ALARMS

Alarm Break

Control and Status

Power	Off	Tx	Ra1 Standby
Loop	Off		Ra2 +21 dBm
Test Port	Off	Rx	Ra1 -33.5 dBm
Transmitter	On		Ra2 -33.5 dBm
Switch Mode	Auto		

914g: MLE_1+1 Major

ALARMS

Alarm Break

Control and Status

Power	Off	Tx	Ra1 Standby
Loop	Off		Ra2 +21 dBm
Test Port	Off	Rx	Ra1 -37.0 dBm
Transmitter	On		Ra2 -32.2 dBm
Switch Mode	Auto		


Scan

Scanning is in progress.

Press (Ctrl+B) to break.

Break

2008 Nov 28 13:48:29 Wake-up msg from unknown ID: "970b" (Subnet id 1). 2008 Nov 28 13:48:40



MINI-LINK Service Manager - [Control Operator]

Setup Log View Misc Window Help

927a: MLE_1+1 Normal

ALARMS

Control and Status

Prank	Off	Ta	Ra1 +25 dBm
Loop	Off	Ra2	Standby
Test Port	Off	Rx	Ra1 -45.3 dBm
Transmitter	On	Ra2	-00.6 dBm
Switch Mode	Auto		

914d: MLE_1+1 Critical

ALARMS

Control and Status

Prank	Off	Ta	Ra1 +25 dBm
Loop	Off	Ra2	Standby
Test Port	Off	Rx	Ra1 -44.1 dBm
Transmitter	On	Ra2	-49.7 dBm
Switch Mode	Auto		

2008 Nov 28 13:54:08 Wake-up msg from unknown ID: '989m' (Submit id 1). 2008 Nov 28 13:54:19

